

STG, INC. DAILY REPORT

PROJECT NAME: Mooring Points Phase 3 - Kalskag

Pictures Taken Today? NO

FOREMAN: Paul Farmer

Temp/Weather: 50's

DATE: 8/27/2013

Precipitation: Light rain

EQUIPMENT INFORMATION

EQUIPMENT DESCRIPTION	HOURS USED	FUEL PURCHASED	MAINTENANCE & COMMENTS
4-wheeler	6		
chainsaw	6		

FREIGHT

CARRIER	DESCRIPTION

SAFETY COMMENTS/CONCERNS

Chain saw safety, slips, trips and falls and watching for local traffic

WORK NARRATIVE

Rented 4-wheeler and chain saw and went over to Site Location 141, measured off area and started clearing brush.

Change In Site Conditions Yes ☐ No ☐ If yes, provide description.

EMPLOYEES & ACTIVITIES

NAME	HOURS	WORK DESCRIPTION/LOCATION
Paul Farmer	6	Clearing brush
Hant T. Alyosius	6	Clearing brush